ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0018	NA	Shettihalli main road
Unique Road No.	**Length of full Road(m)**	
13-W0018-9200	47.00	

Road Details

Road From	Road To
Old Junjappa Temple Road	Dead end
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
42.00	4.20			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	Covered BS Slabs		BS Slab		North

Other Flow Direction Type	Length (m)	Average Width(m)
	0.00	0.00

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	Covered BS Slabs		BS Slab		North

Other Flow Direction Type	Length (m)	Average Width(m)
	0.00	0.00

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
	0		

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	0
Others			

Inspection Details

Number of Trees 0

Date of Inspection 17/07/2015

Name nagabhushan

Remarks

Any Other Information

Category	Image	Photo Remark
Road Condition		
Segment End		
Segment Start		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0022	NA	Old junjappa temple road
Unique Road No.	**Length of full Road(m)**	
13-W0022-9206	88.00	

Road Details

Road From	Road To
Old junjappa temple road	Dead end
Type of Road	**Other Road Type**
Others	Minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
66.00	4.50			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	Covered BS Slabs		BS Slab		North

Other Flow Direction Type	Length (m)	Average Width(m)
	66.00	0.60

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	Covered BS Slabs		BS Slab		North

Other Flow Direction Type	Length (m)	Average Width(m)
	66.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
	0		

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	0
Others			

Inspection Details

Number of Trees 0 **Date of Inspection** 17/07/2015

Name nagabhushan **Remarks**

Any Other Information

Category	Image	Photo Remark
Road Condition		
Segment End		
Segment Start		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0026	NA	Old Junjappa temple road
Unique Road No.	**Length of full Road(m)**	
13-W0026-9224	59.00	

Road Details

Road From	Road To
Old Junjappa temple road	Dead end
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
58.00	5.00			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	Covered BS Slabs		BS Slab		North

Other Flow Direction Type	Length (m)	Average Width(m)
	58.00	0.60

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	Covered BS Slabs		BS Slab		North

Other Flow Direction Type	Length (m)	Average Width(m)
	58.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
RCC deck slab		4.80	1.80

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	2
Others			

Inspection Details

Number of Trees 0 **Date of Inspection** 17/07/2015

Name nagabhushan **Remarks**

Any Other Information

Category	Image	Photo Remark
Road Condition		
Segment End		
Segment Start		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0031	NA	Shettihalli Main road
Unique Road No.	**Length of full Road(m)**	
13-W0031-9232	26.00	

Road Details

Road From	Road To
Shettihalli Main road	Dead end
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
86.00	5.00			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	BS Slab		74.00	1.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	Concrete		74.00	1.00	0	0.00	

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	Covered BS Slabs		BS Slab		East

Other Flow Direction Type	Length (m)	Average Width(m)
	74.00	0.60

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	Covered BS Slabs		BS Slab		East

Other Flow Direction Type	Length (m)	Average Width(m)
	74.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
RCC deck slab		4.30	2.00

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	0
Others			

Inspection Details

Number of Trees 0 **Date of Inspection** 17/07/2015

Name nagabhushan **Remarks**

Any Other Information

Category	Image	Photo Remark
Road Condition		
Segment End		
Segment Start		